

CORE BUYING GUIDE

October 2026



4972 Boiling Brook Parkway
Rockville, MD 20852
Tel: 301 770 4514
Cell: 240 401 0251

Saul@goldfarbinc.com
www.goldfarbinc.com

[Check out our website!](http://www.goldfarbinc.com)

CBG is good for month shown above. All parts are due in by the end of the month. Prices are NOT GUARANTEED to remain at current level.



Goldfarb & Associates Inc. is a diesel parts brokerage company located in Rockville, Maryland. We specialize in diesel injection pumps, injectors, and turbocharger cores.

This CORE BUYING GUIDE shows the parts we are currently buying together with our quality criteria. The guide is updated monthly so please check back for our latest update. If you have parts to sell that are not shown here, please send us your list and we will advise which parts we can accept.

WE PAY ALL SHIPPING COSTS FOR POs THAT ARE \$2000 OR HIGHER.

Our company is built on the highest standards of quality and customer service. It is important that you review the quality criteria for each part described in this guide so you know what we will accept.

Be safe and take care.

Saul Goldfarb


President

Goldfarb & Associates Inc

GOLDFARB & ASSOCIATES INC QUALITY CRITERIA


Fuel Injection Pumps

- No burned units.
- No units that have been dismantled or are missing parts.
- Units must be able to turn (when appropriate).
- Plastic electronic connectors must be in good condition.
- No excessive rust. Units that have been stored outdoors are likely to be scrap.



Ambac Model 100


\$40.00



Bosch P7100 Cummins Commercial

\$200.00


Part Numbers: 0-402-736-XXX; 0-402-746-XXX



Bosch P7100 Dodge 5.9L (0-402-736-XXX only)

\$200.00


(0-402-736-XXX only)



Bosch VE

\$40.00

Not Accepting Automotive Applications



Bosch VE Dodge 5.9L


\$150.00

Dodge part numbers: 0-460-426-103/114/184/205




Cat/Perkins 9.3L Motor

\$200.00




Caterpillar 3116

\$5.00




**Caterpillar 3116/3126 Old Style HPOP
(Round Top)**


\$125.00



Caterpillar 3126 New Style HPOP (Flat Top)
\$125.00




Caterpillar 3208 Naturally Aspirated
\$60.00



Caterpillar 3208 Turbo
\$60.00




Caterpillar 3304 / 3306 New Scroll
\$50.00




Caterpillar 3304 4N145

\$50.00



Caterpillar 3406B Mechanical


\$50.00



Caterpillar C7/C9 HPOP

\$200.00


\$75 if plug is damaged. Pump must turn.



Caterpillar Perkins C6.4L & C6.6L

\$150.00


Must have good solenoids.



Cummins "MW"


\$100.00

Part # 0-403-436-102; -104; -109




Cummins AFC VS

\$75.00




Cummins CAPS 1

\$500.00




Cummins CAPS 2

\$100.00



Cummins Celect N14

\$60.00




Cummins Dual Spring R/H

\$100.00



Cummins ISX12 (without ribs)

\$200.00



Cummins ISX15

\$200.00


Part # 2872662 / 4307527 / 4307700



Cummins VP30

400.00


\$150.00 If plastic electronic plug is damaged.



Cummins VP44

\$250.00


\$100.00 If plastic electronic plug is damaged. Pump must turn.



Delphi DP200/210/300


\$50.00

Accepting All Part Numbers 8520 (and above)



Denso Common Rail

\$25.00



Detroit DD13/DD15 Pump


\$75.00

Bosch part # 0-445-020-235 ; 0-445-020-236




Detroit Gear Pump

\$10.00



Ford 6.0L Aluminum HPOP

\$150.00



Ford 6.0L V8 Cast Iron HPOP

\$75.00


Ford 6.0L V8 Cast Iron 2004.5 - 2010
* Not Buying Navistar V6 Type



Ford 6.4L Siemens HPOP


\$60.00

\$60.00 each - MUST HAVE UNDAMAGED PLUGS
No Damaged Units.




Ford 6.9L

\$50.00




Ford 7.3 Aluminum HPOP

\$125.00




Ford 7.3 Stanadyne DB2

\$50.00



GM 6.2 Stanadyne


NOT CURRENTLY BUYING



GM 6.5 Stanadyne Mechanical

\$50.00

Part #'s DB2831-4911; 4970; 5079; 5088; 5119; 5149;
5157; 5209; 5434; 5436; 5437; 5438; 5485; 5827; 5942



GM 6.5L DS

\$100.00

Part # 5067, 5068, 5288, 5459, 5521, 5942DS-5288,
5459, 5521, 5942, DS-5067, 5068 & more...


No broken plastic components* **Shaft must turn*



GM Duramax 6.6L CP3


\$50.00

LB7 (01-04) = 0-445-020-005/017
LLY (04-05) = 0-445-020-030
LBZ / LMM (06-10) = 0-445-020-037/105



John Deere Bosch

NOT CURRENTLY BUYING



John Deere Bosch Electronic

\$150.00

Part # 0-402-196-XXX



John Deere Stanadyne DE


\$75.00



Lucas / CAV / Delphi (Non DP200, 210 Styles)


\$15.00

Must be complete & turn.



**Navistar Aluminum DT 466/DT530/I530
HPOP**


\$125.00



Navistar Maxxforce 0-445-020-126

\$50.00

0-445-020-126
Plugs must be good.



Navistar Maxxforce HPOP


\$25.00



Simms/Minimec 4 & 6 Cylinder


\$75.00

Pump must turn.
Any 6 Cylinder pump whose first three digits start
with P56XXX or P57XXX.



**Stanadyne & Roosa Master - John Deere /
Case / Caterpillar / Perkins (Agricultural &
Industrial) DBG; DM; JDB; JDM**


\$100.00



**Stanadyne - Caterpillar / Perkins / Case
(Agricultural & Industrial) DB2 & DB4**

\$125.00


These do not include GM5.7, 6.2, and 6.5 and Ford 6.9/7.3. All units must turn
and be complete.



**Stanadyne - John Deere (Agricultural &
Industrial) DB2 & DB4**

\$125.00

These do not include GM5.7, 6.2, and 6.5 and Ford 6.9/7.3. All units must turn
and be complete.



New - Rebuilt Turbochargers & Pumps & Injectors

Price: \$150.00 +

Must get list approved beforehand.

GOLDFARB & ASSOCIATES INC

QUALITY CRITERIA

Fuel Injector Cores

- No burned units
- No units that have been dismantled or are missing parts
- No broken tips (except Detroit Series 60 Part 5000. & up)
- No cut wire harnesses
- Plastic electronic connectors must be in good condition
- No excessive rust.
- Units that have been stored outdoors are likely to be scrap
- No damaged or bent electrical studs (Bosch solenoids)
- Part #'s must be legible
- No plier marks on shafts

Examples of Damaged Fuel Injectors



Damaged Ford 6.0
Injector Plug



Damaged Dodge CR
Injector



Damaged CAT C7/C9
Injector



Caterpillar 3116 Mechanical

20.00



Caterpillar 3126 HEUI Side Mount

NOT CURRENTLY BUYING



Caterpillar 3126 HEUI Top Mount


\$60.00

Top Solenoid Style Only.
Must have good solenoid;
No burned or damaged units.



**Caterpillar 3176/C10/C12 - Must have a
Ceramic Solenoid and legible Part #**

\$20.00



Caterpillar 3406E/C15

\$75.00



Caterpillar 3408 / 3412

\$25.00



**ONE PIECE
BODY
ONLY**

Caterpillar 3500 (One Piece Body Only)

\$75.00



Caterpillar 7000 Series Pencil

\$3.00

* One Piece Body Only, \$25.00 deduction for damaged solenoid.



Caterpillar C13

Must have black band and plunger with hole on top.

NOT CURRENTLY BUYING



Caterpillar C7

\$55.00

These part numbers only: 10R4761, 10R4762, 10R4763, 10R4764, 222-5961, 222-5962, 226-7681, 233-3534, 223-3535, 233-3536, 235-5518, 236-0953, 236-0973, 236-0974, 238-8091, 238-9808, continued...



Caterpillar C9

\$90.00

These part numbers only: 10R7222, 10R7224, 10R7225, 188-8739, 217-2570, 235-2888, 236-0962, 254-4339, 263-8218, 267-3360, 293-4072, 328-2574.



Caterpillar E3

\$85.00

4 Pins



**Chevrolet Duramax 6.6L (LBZ) 2006-2007
#0-445-120-042**

\$15.00



**Chevrolet Duramax 6.6L (LGH) 2011+ #0-
445-117-008**

\$10.00



**Chevrolet Duramax 6.6L (LLY) 2004.5-
2005 #0-445-120-027**

\$35.00



**Chevrolet Duramax 6.6L (LMM) 2007-2010
#0-445-120-082**

\$15.00



**Chevrolet Duramax L5P #12696966;
12678992**
\$30.00



Cummins 24 Valve Mechanical
\$3.00



Cummins 5.9L 12 Valve
\$7.00

KDAL59-P5,6,7,9,12,16
Must have edge filter as shown in photo.



Cummins Celect M11 with Allen Bolt
\$60

No plier marks on body.



Cummins Celect M11 with Flat Bolt

\$60.00



Cummins Celect N14 with Cup Spacer

\$25.00

No plier marks on body.



Cummins HPI ISX

\$30.00

Must have LINK on top. No fake tips accepted. Pressure plugs on tip must be intact.



Cummins PTD Fuel Injector

\$0.50



Cummins STC

\$25.00

Should have metal link. No plier marks on body.



Cummins Top Stop

\$5.00

Must have ridge



Cummins XPI (Pegasus)

\$20.00



Cummins XPI ISX15

\$50.00



Delphi F2 Non-Pumping And Pumping Fuel Injector
\$50.00



Delphi F2E Pumping Fuel Injector
\$50.00



Delphi Paccar EUP
\$50.00

Part Numbers: 1871117, 1934322, 2034927, 2102391



Detroit 92 Electronic
NOT CURRENTLY BUYING



Detroit Diesel 149 Mechanical (Offset)

\$10.00



Detroit Diesel DD13/15

\$20.00



Detroit Diesel E3 (4 pin)

\$75.00

Part # PE4E00001; RFE4E00001; FE4E0001



Detroit Diesel N3

\$75.00

0-414-703-002; 0-414-703-003
0-414-703-005; 0-414-703-007
0-986-441-028; 0-986-441-029
0-986-441-030; 0-986-441-031
Not buying if damaged plug;
Must be able to read the Part #



Detroit N, C & 92 Series Mechanical

\$20.00

NC92 has 2 notches on hex \$20.00.
HV & S Type have 1 notch or no notches on hex = No Value!



Detroit Series 60 (5000 and above)

\$80.00

Part #'s 5000 & UP only.



**Dodge Cummins 6.7L Common Rail
2007.5-2015**

\$25.00

We are buying only these Part #'s: 0-445-120-050 or
185 or 193 0-445-120-071 or 184 or 204 0-986-435-518
or 519



Ford 6.0L Powerstroke 2003-2007

\$15.00



Ford 6.4L Powerstroke 2008-2010

NOT CURRENTLY BUYING



Ford 6.7 with Blue Arm 2011-2014 (0-445-117-023/024)

\$10.00



Ford 6.7L Powerstroke

\$10.00

Part # 0-445-118-028
With "Pink Arm"



← GREY ARM

Ford 6.7L Powerstroke with grey arm 2015-2019

\$20.00

Part # 0-445-117-040



Ford 6.9/7.3 IDI Mechanical

\$1.50



Ford 7.3L Powerstroke AA

\$20.00



Ford 7.3L Powerstroke AB

\$20.00



Ford 7.3L Powerstroke AD

\$25.00



Ford 7.3L Powerstroke AE

\$20.00



Ford Powerstroke 6.7L 2011 - 2014

\$0.00

Part # 0-445-117-024



GM 6.2 & 6.5 Mechanical

\$1.50



International DT466

NOT CURRENTLY BUYING



Jeep 3.0L Diesel

\$5.00



John Deere Denso

095000-6310; 095000-6320
RE546784; RE531209; RE530362
RE546783; RE531210; RE530361
NOT CURRENTLY BUYING



John Deere Denso CR

Must have good solenoid.
No Isuzu, Fuso or Hino.
NOT CURRENTLY BUYING



L'Orange

\$50.00
Part # 5940-750-0020
Part # 5240-750-0053
NOT CURRENTLY BUYING



Mack EUP

\$10.00



Mercedes MBE4000

\$40.00

Part numbers: A4600170312; A0030179112



**Mercedes Sprinter 2001-2006 04451062
0986435129 04451063 0986435109
0445110162 0445110181**

\$5.00



Mercedes Sprinter Late 2007-2010

\$5.00



Navistar DT466 BA BB BC BD BE BF

\$35.00



Navistar DT466 BI BJ BN BP

\$50.00



Navistar G2.9 DT466/DT570/Maxxforce

NOT CURRENTLY BUYING



Paccar M13

\$20.00



Volvo 2 Pin

\$10.00



Volvo 4 Pin

\$10.00

All Part #'s



Volvo with Ceramic Solenoid

\$25.00

NOTE: Must have "W" or "Y" letter on body



VW 1.9L TDI

038-130-073, 0-414-720-215, and 0-414-720-265.

\$25.00 each

NOT CURRENTLY BUYING

GOLDFARB & ASSOCIATES INC

QUALITY CRITERIA

IMPORTANT!

Turbocharger Cores

1. **No burned units**
2. **No units that have been dismantled or are missing parts**
3. **No excessive rust. Units that have been stored outdoors are likely to be scrap**
4. **Plastic electronic connectors must be in good condition**
5. **Damage to compressor or exhaust wheel (fan) will result in deductions or scrap unit.**
6. **Side to side or in and out play of shaft will result in deductions or scrap unit.**
7. **Damage to compressor or exhaust housings will result in deductions or scrap unit.**
8. **Missing or damaged waste gate actuators will result in deductions or scrap**
9. **Chinese aftermarket units have no value**


Want to know how we check the quality of our turbocharger cores? Take a look at this video:
<http://youtu.be/YrvVuKUs5oE>



2015+ Ford 6.7L F250 Powerstroke

\$50.00

Part Numbers Starting FC + HC Only.



Automotive

NOT CURRENTLY BUYING



Caterpillar 3406E

\$65.00

No value for damaged units.



Caterpillar ACERT C13/C15 High Pressure

\$65.00

No value for damaged housing



Caterpillar ACERT C13/C15 Low Pressure

\$50.00



Caterpillar C7/C9

NOT CURRENTLY BUYING



Chevrolet 6.5L GM8 Only

NOT CURRENTLY BUYING



**Chevrolet Duramax 6.6L (LB7) 2001-
2004.5**

IHI Turbo.

NOT CURRENTLY BUYING



**Chevrolet Duramax 6.6L (LB7) 2001-
2004.5 California Emissions**

Part # 8972541603

NOT CURRENTLY BUYING



Chevrolet Duramax 6.6L (LBZ) 2006-2007

\$50.00



**Chevrolet Duramax 6.6L (LLY) 2004.5-
2005**

\$50.00



Chevrolet Duramax 6.6L (LML/LGH) 2011+

\$50.00



Chevrolet Duramax 6.6L (LMM) 2008-2011

\$50.00

NOT CURRENTLY BUYING



Chevrolet Duramax L5P


\$175.00



Cummins Dodge Ram HE300VG + HE351VE

\$175.00

Good units \$250.00. Damaged units \$125.00



Cummins Electronic VGT Turbocharger Actuator Core

\$135.00

HE300VG Actuator. No value for damaged.
The HE351VE actuators (with wire) are \$75 each.



**Cummins Holset HE300VG / HE351VE
Industrial**
\$250.00



Cummins Holset HE341VE
\$200.00



Cummins Holset HT60
\$65.00
Good units only!



Cummins Holset HX55W
\$90.00



Cummins Holset HX60W

\$100.00



Cummins Holset HX83 and HT100

\$125.00



**Cummins Holset Wastegated HX30 /
HX30W**

\$65.00



**Cummins Holset Wastegated
HX35W, HX40W, WH1E, WH1C**

NOT CURRENTLY BUYING



Cummins ISX Holset HE431VE / HE451VE / HE400VG

\$175.00

\$250.00 each if good. \$125.00 each if damaged. Must have the electronic actuator.



Cummins ISX Holset HE500VG / HE551VE / HE561VE

\$175.00

\$250.00 each if good. \$100.00 each if damaged. Must have the electronic actuator.



Cummins ISX Holset HE551V


\$150.00

\$150 each if good. \$50.00 each if damaged. Must have a mechanical actuator.



Cummins M11 Holset HX55

NOT CURRENTLY BUYING



Daimler Detroit Diesel DD13/DD15

\$125.00

Part # A4720901480



Detroit 14L

\$50.00

\$25.00 If damaged or missing actuator.



Detroit Series 60 12.7L Wastegated

\$65.00

No value on damaged units. Garrett only.



Detroit Series 60 Non-Wastegated

\$50.00

No value on damaged units. Garrett only.



Dodge 5.9L Cummins HE341CW

NOT CURRENTLY BUYING



Dodge Cummins 5.9L Holset HE351CW
2004.5-2007

NOT CURRENTLY BUYING



Ford 6.0L


\$35.00

NOT CURRENTLY BUYING



Ford 6.4L Dual

NOT CURRENTLY BUYING



Ford 6.4L Turbo Actuator


\$25.00



Ford 6.9/7.3 IDI

\$35.00

Part #'s 466533-1, 2, 3, 4, 5, 6, 1819744C92, 1821328C91, 1821329C91.



Ford 7.3L Powerstroke GTP38

Large compressor housing only. Exhaust side 7 Bolt pattern only - shown on image. Years 1995.5 and higher only. No value on damaged units. With proper vertical Actuator Nipple - not horizontal.

NOT CURRENTLY BUYING



**Ford 7.3L Powerstroke GTP38 Mid Year
1998- 1999**

Part Numbers 1825878C91 / C92

NOT CURRENTLY BUYING



Ford Powerstroke 6.7L Scorpion

NOT CURRENTLY BUYING



Ford Powerstroke 6.7L Single Outlet

NOT CURRENTLY BUYING



Holset Cummins ISX HX55

\$90.00


Part # 3595090, 4036892, 4089754...others



Holset Detroit Diesel DD15 HX55

\$125.00

Part # 3768075...plus others



Holset HE400/451 Volvo Mack

\$150.00



Holset HE531VE Detroit Diesel

\$250.00

Part # 2836825, 4043261, 4045291, 23539570,
23539062...



Holset Non-Wastegated H1C / H1E

No value for damaged units.

NOT CURRENTLY BUYING



Holset Non-Wastegated H2C / H2D / H2E

\$35.00

No value for damaged units.



Holset Non-Wastegated HT3B

No value for damaged units.

NOT CURRENTLY BUYING



Holset Paccar HE500VG / HE531VE

\$350.00

Part # 2842125, 3767294, 1831156.



**International 6.0L VT 365
Industrial/Commercial App**

Six Blade Compressor Wheel

NOT CURRENTLY BUYING



International DT466E Borg Warner B2V

\$100.00

NOTE: V-Band Turbine Housing



International DT466E Borg Warner S300V

\$100.00

NOTE: Bolted Turbine Housing.



**International MaxxForce Twin Turbos 9 /
10 / 11 / 13 / 15**

\$100.00

\$100.00 for the set.

\$50.00 / side



Mack BWTS E7

(Upturn Compressor Cover Only)


NOT CURRENTLY BUYING



Mack S430V

\$175.00

NOTE: Must Have Good Electronics.




Marine

\$100-\$150 Good units.
\$50 Damaged units.




Mercedes Sprinter w/actuator

NOTE: Must Have Good Electronic Actuator.
NOT CURRENTLY BUYING



Nissan Titan Cummins Twin Turbo



\$150.00



Duramax L5P Actuators

\$75.00

2017 - 2019 Duramax L5P - Part # 12723306; 12708802
2020 - 2023 Duramax L5P - Part # 186217036; 59001107489;
12707578; 12723081
We will accept more part numbers.



New - Rebuilt Turbochargers & Pumps & Injectors

\$150.00 +

Must get list approved beforehand.



Cummins EGR Valve

\$10.00



Cummins ISX Solenoid

\$20.00



Cummins ISX15 EGR Valve

\$10.00

Part Numbers: 2881762, 4352302, 5406049, 5411635



Detroit Accessory Drive

NOT CURRENTLY BUYING




Detroit EGR Valve

\$25.00



Detroit Series 60 Gear Pump

\$10.00



Detroit VPOD Cores

\$60.00

No value for broken plug.

Program: DDE6 Group: S50/60 VPOD

C23530299 R23530299/CR

C23530736 R23530736/CR

C23536813 E - R 23536813/CR

C23536814 E - R 23536814/CR

C23536834 E - R 23536834/CR

C23536835 E - R 23536835/CR



DD13 and DD15 DEF Pumps

\$40.00



Ford 7.3 Throttle Shaft


\$20.00

Part # 23588



Freightliner NOX Sensors

\$20.00




Holset Actuator Control Valve

\$40.00



Hydraulic Gear Pump

\$25




International Maxxforce Navistar 11, 13 EGR Valve 2014-2015

\$40.00

Part # 5010918R92 at \$40.00

Part # 5010696R94 at \$40.00



Tappet for Stanadyne IFS Injector

\$10.00

Tappet for Stanadyne IFS Injector


GOLDFARB & ASSOCIATES INC

QUALITY CRITERIA

IMPORTANT!

ECM Cores

1. **No burned units**
2. **No units that have been dismantled or are missing parts**
3. **No excessive rust. Units that have been stored outdoors are likely to be scrap**
4. **Plastic electronic connectors must be in good condition**
5. **Chinese aftermarket units have no value**



Caterpillar 120 Pin

\$75.00

Cat #s MXS, SDP, LEE, NXS



Caterpillar 40 Pin

\$75.00

Cat #s 1LW, 5EK, 6TS



Caterpillar 70 Pin

\$75.00

Cat #s 157-3705, 162-7584, 259-1159, 240-5303, 206-2700, 179-4899



Cummins Celect & Celect Plus

\$100.00



Cummins ISX

\$75.00

Cummins # 3684009 (CM870), 3684275 (CM871)



Cummins ISX15

\$75.00

Cummins # 4358814



Detroit DDEC III and IV ECM

\$100.00

No water or fire damage.
Plugs can not be damaged.
No disassembled units.



Detroit Diesel DDEC III

\$100.00

Detroit #s 23513553, 23518645, 23518743



Detroit Diesel DDEC IV

\$175.00

Detroit #s 23519307, 23519308



Detroit Diesel DDEC V

\$175.00


Detroit #s 23530802, 23535798, 23535990



Duramax LLY FICM

\$75.00

Part Numbers # 0-281-011-134 , 97303751



Ford 6.0L FICM

\$50.00

Navistar # 1845117C1/2/3/4/ , 4307224R1, 4307211R93



Ford 7.3L IDM

\$100.00

Part Numbers # IDM100, IDM110, IDM120



Freightliner CPC4 Module

\$100.00


A 003 446 10 02 / 005



International Maxxforce

Part Numbers # 3007009C2, 5010979R1, 5010980R1, 0-281-020-159


NOT CURRENTLY BUYING



International Maxxforce DT

International # 1881708C91, 1883086C93

NOT CURRENTLY BUYING



Paccar MX13

\$175.00



V-Mac & II

\$100.00


Part #s 0-281-001-095, 12MS51M, 12MS59M
* Note: If the ECM is not the numbers listed, price reduced to \$50.00



V-Mac E7

\$100.00

Part #s 0-281-001-095, 12MS45M2
* Note: If the ECM is not the numbers listed, price reduced to \$50.00



Volvo Mack MP7, MP8, D12, D13

\$50.00

Part #s 20412511, 20561256, 20583789, 20814620, 20814642, 20977021, 21042371, 21107008, 21300060, 21358126, 21900553, 22581042

Table of Contents

Product	Page
FUEL INJECTION PUMPS	3
Ambac Model 100	<u>4</u>
Bosch P7100 Cummins Commercial	<u>4</u>
Bosch P7100 Dodge 5.9L (0-402-736-XXX only)	<u>4</u>
Bosch VE	<u>4</u>
Bosch VE Dodge 5.9L	<u>5</u>
Cat/Perkins 9.3L Motor	<u>5</u>
Caterpillar 3116	<u>5</u>
Caterpillar 3116/3126 Old Style HPOP (Round Top)	<u>5</u>
Caterpillar 3126 New Style HPOP (Flat Top)	<u>6</u>
Caterpillar 3208 Naturally Aspirated	<u>6</u>
Caterpillar 3208 Turbo	<u>6</u>
Caterpillar 3304 / 3306 New Scroll	<u>6</u>
Caterpillar 3304 4N145	<u>7</u>
Caterpillar 3406B Mechanical	<u>7</u>
Caterpillar C7/C9 HPOP	<u>7</u>
Caterpillar Perkins C6.4L & C6.6L	<u>7</u>
Cummins "MW"	<u>8</u>
Cummins AFC VS	<u>8</u>
Cummins CAPS 1	<u>8</u>
Cummins CAPS 2	<u>8</u>
Cummins Celect N14	<u>9</u>
Cummins Dual Spring R/H	<u>9</u>
Cummins ISX12 (without ribs)	<u>9</u>
Cummins ISX15	<u>9</u>
Cummins VP30	<u>10</u>
Cummins VP44	<u>10</u>
Delphi DP200/210/300	<u>10</u>
Denso Common Rail	<u>10</u>
Detroit DD13/DD15 Pump	<u>11</u>
Detroit Gear Pump	<u>11</u>
Ford 6.0L Aluminum HPOP	<u>11</u>
Ford 6.0L V8 Cast Iron HPOP	<u>11</u>
Ford 6.4L Siemens HPOP	<u>12</u>
Ford 6.9L	<u>12</u>
Ford 7.3 Aluminum HPOP	<u>12</u>
Ford 7.3 Stanadyne DB2	<u>12</u>
GM 6.2 Stanadyne	<u>13</u>
GM 6.5 Stanadyne Mechanical	<u>13</u>

Table of Contents

Product	Page
GM 6.5L DS	<u>13</u>
GM Duramax 6.6L CP3	<u>13</u>
John Deere Bosch	<u>14</u>
John Deere Bosch Electronic	<u>14</u>
John Deere Stanadyne DE	<u>14</u>
Lucas / CAV / Delphi (Non DP200, 210 Styles)	<u>14</u>
Navistar Aluminum DT 466/DT530/I530 HPOP	<u>15</u>
Navistar Maxxforce 0-445-020-126	<u>15</u>
Navistar Maxxforce HPOP	<u>15</u>
Simms/Minimec 4 & 6 Cylinder	<u>15</u>
Stanadyne & Roosa Master - John Deere / Case / Caterpillar / Perkins (Agricultural & Industrial) DBG; ...	<u>16</u>
Stanadyne - Caterpillar / Perkins / Case (Agricultural & Industrial) DB2 & DB4	<u>16</u>
Stanadyne - John Deere (Agricultural & Industrial) DB2 & DB4	<u>16</u>
New - Rebuilt Turbochargers & Pumps & Injectors	<u>17</u>
FUEL INJECTOR CORES	<u>18</u>
Caterpillar 3116 Mechanical	<u>19</u>
Caterpillar 3126 HEUI Side Mount	<u>19</u>
Caterpillar 3126 HEUI Top Mount	<u>19</u>
Caterpillar 3176/C10/C12 - Must have a Ceramic Solenoid and legible Part #	<u>19</u>
Caterpillar 3406E/C15	<u>20</u>
Caterpillar 3408 / 3412	<u>20</u>
Caterpillar 3500 (One Piece Body Only)	<u>20</u>
Caterpillar 7000 Series Pencil	<u>20</u>
Caterpillar C13	<u>21</u>
Caterpillar C7	<u>21</u>
Caterpillar C9	<u>21</u>
Caterpillar E3	<u>21</u>
Chevrolet Duramax 6.6L (LBZ) 2006-2007 #0-445-120-042	<u>22</u>
Chevrolet Duramax 6.6L (LGH) 2011+ #0-445-117-008	<u>22</u>
Chevrolet Duramax 6.6L (LLY) 2004.5-2005 #0-445-120-027	<u>22</u>
Chevrolet Duramax 6.6L (LMM) 2007-2010 #0-445-120-082	<u>22</u>
Chevrolet Duramax L5P #12696966; 12678992	<u>23</u>
Cummins 24 Valve Mechanical	<u>23</u>
Cummins 5.9L 12 Valve	<u>23</u>
Cummins Celect M11 with Allen Bolt	<u>23</u>
Cummins Celect M11 with Flat Bolt	<u>24</u>
Cummins Celect N14 with Cup Spacer	<u>24</u>
Cummins HPI ISX	<u>24</u>
Cummins PTD Fuel Injector	<u>24</u>
Cummins STC	<u>25</u>

Table of Contents

Product	Page
Cummins Top Stop	<u>25</u>
Cummins XPI (Pegasus)	<u>25</u>
Cummins XPI ISX15	<u>25</u>
Delphi F2 Non-Pumping And Pumping Fuel Injector	<u>26</u>
Delphi F2E Pumping Fuel Injector	<u>26</u>
Delphi Paccar EUP	<u>26</u>
Detroit 92 Electronic	<u>26</u>
Detroit Diesel 149 Mechanical (Offset)	<u>27</u>
Detroit Diesel DD13/15	<u>27</u>
Detroit Diesel E3 (4 pin)	<u>27</u>
Detroit Diesel N3	<u>27</u>
Detroit N, C & 92 Series Mechanical	<u>28</u>
Detroit Series 60 (5000 and above)	<u>28</u>
Dodge Cummins 6.7L Common Rail 2007.5-2015	<u>28</u>
Ford 6.0L Powerstroke 2003-2007	<u>28</u>
Ford 6.4L Powerstroke 2008-2010	<u>29</u>
Ford 6.7 with Blue Arm 2011-2014 (0-445-117-023/024)	<u>29</u>
Ford 6.7L Powerstroke	<u>29</u>
Ford 6.7L Powerstroke with grey arm 2015-2019	<u>29</u>
Ford 6.9/7.3 IDI Mechanical	<u>30</u>
Ford 7.3L Powerstroke AA	<u>30</u>
Ford 7.3L Powerstroke AB	<u>30</u>
Ford 7.3L Powerstroke AD	<u>30</u>
Ford 7.3L Powerstroke AE	<u>31</u>
Ford Powerstroke 6.7L 2011 - 2014	<u>31</u>
GM 6.2 & 6.5 Mechanical	<u>31</u>
International DT466	<u>31</u>
Jeep 3.0L Diesel	<u>32</u>
John Deere Denso	<u>32</u>
John Deere Denso CR	<u>32</u>
L'Orange	<u>32</u>
Mercedes MBE4000	<u>33</u>
Mack EUP	<u>33</u>
Mercedes Sprinter 2001-2006 04451062 0986435129 04451063 0986435109 0445110162 0445110181	<u>33</u>
Mercedes Sprinter Late 2007-2010	<u>33</u>
Navistar DT466 BA BB BC BD BE BF	<u>34</u>
Navistar DT466 BI BJ BN BP	<u>34</u>
Navistar G2.9 DT466/DT570/Maxxforce	<u>34</u>
Paccar M13	<u>34</u>
Volvo 2 Pin	<u>35</u>

Table of Contents

Product	Page
Volvo 4 Pin	35
Volvo with Ceramic Solenoid	35
VW 1.9L TDI	35
TURBOCHARGER CORES	36
2015+ Ford 6.7L F250 Powerstroke	37
Automotive	37
Caterpillar 3406E	37
Caterpillar ACERT C13/C15 High Pressure	37
Caterpillar ACERT C13/C15 Low Pressure	38
Caterpillar C7/C9	38
Chevrolet 6.5L GM8 Only	38
Chevrolet Duramax 6.6L (LB7) 2001-2004.5	38
Chevrolet Duramax 6.6L (LB7) 2001-2004.5 California Emissions	39
Chevrolet Duramax 6.6L (LBZ) 2006-2007	39
Chevrolet Duramax 6.6L (LLY) 2004.5-2005	39
Chevrolet Duramax 6.6L (LML/LGH) 2011+	39
Chevrolet Duramax 6.6L (LMM) 2008-2011	40
Chevrolet Duramax L5P	40
Cummins Dodge Ram HE300VG + HE351VE	40
Cummins Electronic VGT Turbocharger Actuator Core	40
Cummins Holset HE300VG / HE351VE Industrial	41
Cummins Holset HE341VE	41
Cummins Holset HT60	41
Cummins Holset HX55W	41
Cummins Holset HX60W	42
Cummins Holset HX83 and HT100	42
Cummins Holset Wastegated HX30 / HX30W	42
Cummins Holset Wastegated HX35W, HX40W, WH1E, WH1C	42
Cummins ISX Holset HE431VE / HE451VE / HE400VG	43
Cummins ISX Holset HE500VG / HE551VE / HE561VE	43
Cummins ISX Holset HE551V	43
Cummins M11 Holset HX55	43
Daimler Detroit Diesel DD13/DD15	44
Detroit 14L	44
Detroit Series 60 12.7L Wastegated	44
Detroit Series 60 Non-Wastegated	44
Dodge 5.9L Cummins HE341CW	45
Dodge Cummins 5.9L Holset HE351CW 2004.5-2007	45
Ford 6.0L	45
Ford 6.4L Dual	45

Table of Contents

Product	Page
Ford 6.4L Turbo Actuator	<u>46</u>
Ford 6.9/7.3 IDI	<u>46</u>
Ford 7.3L Powerstroke GTP38	<u>46</u>
Ford 7.3L Powerstroke GTP38 Mid Year 1998- 1999	<u>46</u>
Ford Powerstroke 6.7L Scorpion	<u>47</u>
Ford Powerstroke 6.7L Single Outlet	<u>47</u>
Holset Cummins ISX HX55	<u>47</u>
Holset Detroit Diesel DD15 HX55	<u>47</u>
Holset HE400/451 Volvo Mack	<u>48</u>
Holset HE531VE Detroit Diesel	<u>48</u>
Holset Non-Wastegated H1C / H1E	<u>48</u>
Holset Non-Wastegated H2C / H2D / H2E	<u>48</u>
Holset Non-Wastegated HT3B	<u>49</u>
Holset Paccar HE500VG / HE531VE	<u>49</u>
International 6.0L VT 365 Industrial/Commercial App	<u>49</u>
International DT466E Borg Warner B2V	<u>49</u>
International DT466E Borg Warner S300V	<u>50</u>
International MaxxForce Twin Turbos 9 / 10 / 11 / 13 / 15	<u>50</u>
Mack BWTS E7	<u>50</u>
Mack S430V	<u>50</u>
Marine	<u>51</u>
Mercedes Sprinter w/actuator	<u>51</u>
Nissan Titan Cummins Twin Turbo	<u>51</u>
Duramax L5P Actuators	<u>51</u>
New - Rebuilt Turbochargers & Pumps & Injectors	<u>52</u>
Cummins EGR Valve	<u>53</u>
Cummins ISX Solenoid	<u>53</u>
Cummins ISX15 EGR Valve	<u>53</u>
Detroit Accessory Drive	<u>53</u>
Detroit EGR Valve	<u>54</u>
Detroit Series 60 Gear Pump	<u>54</u>
Detroit VPOD Cores	<u>54</u>
DD13 and DD15 DEF Pumps	<u>54</u>
Ford 7.3 Throttle Shaft	<u>55</u>
Freightliner NOX Sensors	<u>55</u>
Holset Actuator Control Valve	<u>55</u>
Hydraulic Gear Pump	<u>55</u>
International Maxxforce Navistar 11, 13 EGR Valve 2014-2015	<u>56</u>
Tappet for Stanadyne IFS Injector	<u>56</u>
ECMs	<u>57</u>

Table of Contents

Product	Page
Caterpillar 120 Pin	<u>58</u>
Caterpillar 40 Pin	<u>58</u>
Caterpillar 70 Pin	<u>58</u>
Cummins Celect & Celect Plus	<u>58</u>
Cummins ISX	<u>59</u>
Cummins ISX15	<u>59</u>
Detroit DDEC III and IV ECM	<u>59</u>
Detroit Diesel DDEC III	<u>59</u>
Detroit Diesel DDEC IV	<u>60</u>
Detroit Diesel DDEC V	<u>60</u>
Duramax LLY FICM	<u>60</u>
Ford 6.0L FICM	<u>60</u>
Ford 7.3L IDM	<u>61</u>
Freightliner CPC4 Module	<u>61</u>
International Maxxforce	<u>61</u>
International Maxxforce DT	<u>61</u>
Paccar MX13	<u>62</u>
V-Mac & II	<u>62</u>
V-Mac E7	<u>62</u>
Volvo Mack MP7, MP8, D12, D13	<u>62</u>